

## PT1000

-50°C	803,10 Ohm
-40°C	842,70 Ohm
-30°C	882,20 Ohm
-20°C	921,60 Ohm
-10°C	960,90 Ohm
0°C	1000,00 Ohm
+10°C	1039,00 Ohm
+20°C	1077,90 Ohm
+25°C	1097,40 Ohm
+30°C	1116,70 Ohm
+40°C	1155,40 Ohm
+50°C	1194,00 Ohm
+60°C	1232,40 Ohm
+70°C	1270,70 Ohm
+80°C	1308,90 Ohm
+90°C	1347,00 Ohm
+100°C	1385,00 Ohm
+110°C	1422,90 Ohm
+120°C	1460,60 Ohm
+130°C	1498,20 Ohm
+140°C	1535,80 Ohm
+150°C	1573,10 Ohm

[www.sensorshop24.de](http://www.sensorshop24.de)