

Ni1000

| | |
|---------------|--------------------|
| -50°C | 743,00 Ohm |
| -40°C | 791,00 Ohm |
| -30°C | 842,00 Ohm |
| -20°C | 893,00 Ohm |
| -10°C | 946,00 Ohm |
| 0°C | 1000,00 Ohm |
| +10°C | 1056,00 Ohm |
| +20°C | 1112,00 Ohm |
| +25°C | 1141,00 Ohm |
| +30°C | 1171,00 Ohm |
| +40°C | 1230,00 Ohm |
| +50°C | 1291,00 Ohm |
| +60°C | 1353,00 Ohm |
| +70°C | 1417,00 Ohm |
| +80°C | 1483,00 Ohm |
| +90°C | 1549,00 Ohm |
| +100°C | 1618,00 Ohm |
| +110°C | 1688,00 Ohm |
| +120°C | 1760,00 Ohm |
| +130°C | 1883,00 Ohm |
| +140°C | 1909,00 Ohm |
| +150°C | 1987,00 Ohm |

www.sensorshop24.de